

Customer Services Bulletin 27/03/2020 TB-M-0047 – TB-C-0055



Re: Dometic Fridge Condenser Pipe

Dear Colleague,

Following an inspection of products fitted with the new Dometic 10-series 153 litre electronic fridge freezer (with universal handed door mechanism) it has been identified that the condenser pipe may have not have been correctly secured in its retaining clip.

The purpose of this pipe is to evacuate water from the fridge freezer outside the vehicle through the lower exterior vent. If it is not secured there is the possibility that any water discharged will be directed inside the vehicle. This is of particular concern when the fridge freezer is defrosted.

Vehicles affected include selected models from the Autograph III motorhome range and all models from the Alicanto Grande I caravan range.

Autograph III Models affected: Autograph 79-2F, 79-4F, 79-4I, 79-4T & 81-6 Autograph III VIN sequences:

- Autograph III 79-2F & 79-4F 79F06770 79207459
- Autograph III 79-4i 79i06549 79i07490

Autograph III 79-4T
Autograph III 81-6
79T06794 - 79T07500
81606844 - 81607413

Alicanto Grande I VIN sequence:

• Estoril, Sintra & Porto LAO00001 to LAO02659

All models produced after these VIN sequences have already been assessed and cleared for dispatch.

As a precautionary measure, we therefore believe it is necessary for an additional inspection of the models in question and if required the condenser pipe should be secured in place following the attached Standard Operating Procedure SOP (Z-SOP-RPC-P-SP-0011-01). The estimated time required to complete the check and secure the pipe in position would be 15 minutes. The warranty code to be used is: 9999084

I would like to take this opportunity to apologise for any inconvenience that this matter may cause you and your customers, but we thank you in advance for your continued support and assistance.

Best regards


Dave Evans Head of Customer Services





Fridge Water Drain Pipe Fixing

Z-SOP-RPC-P-SP-0011

Document Revision History Revision Reason For Change		
01	Initial Write Up	
	Models	s Affected
	ALL ALICANTO MODELS	AUTOGRAPH 3 MODELS
	ESTORIL	79-2F
	FARO	79-4F
	PORTO	79-4i
	SINTRA	79-4T
		816










Opp 4 Operation Description:



Re-fitting the outer fridge vent cover: Insert fridge vent Right Hand Side first, ensure the top cover engages with X2 clips on Right Hand Side of frame.





Once the right hand side of the cover is fully located, carefully push the left hand side of vent in so both sides are fully locked into position/engaged.

