



Retailer Services Bulletin

TB-C-0058

18/09/2020



Re: Truma Solar Dual Battery Charger

Dear Colleague,

We have become aware of a small number of Truma Solar Dual Battery Chargers that have been incorrectly wired up in Alicanto Grande models.

The VIN range of affected models are: **MAO00063 – MAO00102**

The picture below shows the correct wiring configuration and we would kindly ask that you check the Truma Solar Dual Battery Chargers in any Alicanto models you have on site.

Should any rework be required, please use this warranty code to claim 15 minutes warranty labour: **9999086**



Best regards

Dave Evans
Head of Customer Services